

CERTIFICATE OF COMPLIANCE

Certificate Number 20141022-E169078
Report Reference E169078-20140921
Issue Date 2014-OCTOBER-22

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

USL, CNL - Auxiliary Devices, actuators PRSL1805PI, PRSL1806PI, PRSL1807PI, PRSL1808PI, PRSL1809PI, PRSL1810PI, PRSL1811PI, and PRSL1815PI.

USL, CNL - Auxiliary Devices, Emergency mushroom push-buttons PRSL1880PI and PRSL1881PI.

USL, CNL - Auxiliary Devices, Emergency key mushroom push-buttons PRSL1890PI.

USL, CNL - Auxiliary Devices, Impulse mushroom push-buttons PRSL1882PI and PRSL1885 followed by ROC or NEC;

USL, CNL - Auxiliary Devices, key selector switches PRSL1867PI, PRSL1868PI, PRSL1869PI, PRSL1870PI, PRSL1871PI, PRSL1872PI, PRSL1873PI, PRSL1874PI, PRSL1875PI and PRSL1876PI.

USL, CNL - Auxiliary Devices, selector switches PRSL1855, PRSL1856, PRSL1857, PRSL1858, PRSL1859, PRSL1860, PRSL1861, PRSL1862, PRSL1863 and PRSL1864, followed by BI or VE or BL or RO or GI or AR, maybe followed by C.

USL, CNL - Auxiliary Devices, pilot lights PRSL1840PI, PRSL1841PI, PRSL1842PI, PRSL1843PI, PRSL1844PI and PRSL1846PI

USL, CNL - Auxiliary Devices, blanking Plug PRSL1845PI



Bruce Mahrenholz, Assistant Chief Engineer, Global Inspection and Field Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at www.ul.com/contactus

